

**SECRET**

EPD 1385-59  
Cy 4 of 5  
3 March 1959

25X1A TO :

[Redacted]

**SUBJECT:** Elint Equipment Malfunction Report for February 1959

25X1A

**Detachment C -** Some interference was encountered between [Redacted] equipments in aircraft 370. Corrective action is being taken but has not been completed as of this date.

25X1A

**Detachment B -** A regulated 150 volt supply failed in [Redacted] equipment while on test flight. The supply was repaired and is now functioning properly.

25X1A

[Redacted]

**Distribution:**

Orig & 1 - Addressee  
3 - O-15  
4 - RI  
5 - Chrono

A.W.R./bs

**SECRET**